Sanitized Copy Approved for Release 2010/06/16 : CIA-RDP80T00246A037200270001-9

INFORMATION REPORT INFORMATION REPORT

CENTRAL INTELLIGENCE AGENCY

This material contains information affecting the National Defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C. Secs. 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

OUNTRY East Cermany		REPORT		25
JBJECT Reconstruction at	Stendal Airfield	DATE DISTR.	12 SEP 1867	
		NO. PAGES	1	
		REQUIREMENT NO.	RD	
ATE OF		REFERENCES		
IFO.		PRO	CESSING COPY	25
ACE &		•	CESSING COF!	20
ATE ACQ.	ATIONS ARE DEFINITIVE. AF			
on reconstruction under the followin (3) Hard Stendings and (6) Surface (6)	at Stendal airfield. ag headings: (1) Run a, (4) Power Cables, nstruction. A sketcl	The report give way Details, (2) (5) New Fuel Instance to showing the fe	report es information Taxiway Details, tallation.	
on reconstruction under the following (3) Hard Stendings and (6) Surface Co	at Stendal airfield. ng neadings: (1) Run s. (4) Power Cables.	The report give way Details, (2) (5) New Fuel Instance to showing the fe	report es information Taxiway Details, tallation.	
on reconstruction under the followin (3) Hard Stendings and (6) Surface Co	at Stendal airfield. ag headings: (1) Run a, (4) Power Cables, nstruction. A sketcl	The report give way Details, (2) (5) New Fuel Instance to showing the fe	report es information Taxiway Details, tallation.	_ 25

77

25X1

S-E-C-R-E-IT

STATE ARMY X NAVY X AIR X FBI AEC

STATE ARMY X NAVY X AIR X FBI AEC

(Note: Washington distribution indicated by "X"; Field distribution by "#".)

NFORMATION REPORT INFORMATION REPORT

SECRET 25X1 25X1 AIR/MILITARY STENDAL airfield - Reconstruction 25X1 Aprendix: Attached as an appendix is a rough sketch plan, not drawn to any scale, showing features of the runway and associated hardstandings. RUNWAY DETAILS 1. The replacement of the large number of faults in the main E/W runway has been given the highest priority on the airfield, and to date all but 18 have been completed. These 18 each comprise complete sections, which are being replaced by hand. runway has been swept clear of 25X1 The remainder of this 2000-m debris and will very shortly be completely serviceable. TAXIWAY DETAILS 2. (a) The parallel northern taxiway has been completed, with the exception of a strip approximately 100 m____n length. This 25X1 taxivay is 14 metres in width and consists of four strips, each width, all sections being locked longtitudinally 25X1 by metal rods. The concrete is mostly 18 cms in thickness, but as in the main runway, in places has a thickness of 20 cms. (b) A total of four transverse taxiways, each having a uniform 25X1 has been completed, the taxiways being equally width[spaced approximately 180 m at each end of the runway. 25X1 Each of these transverse taxiways has an identical extensive fillet adjoining each end. There are no signs of a fifth transverse taxiway being laid down and the area contained between the runway/taxiway and the two inner transverse taxiways has been levelled off, and in places where the surface has been disturbed is being sown with grass. 3. HARI STANDINGS (a) $7\,\mathrm{h}$ ard standing [located at the western end of the parallel taxiway, 25X1 has been completed. It is difficult to ascertain at present the final shape of the two ends, as are covered over in 25X1 parts with matting. The digging out of the bordering gulley which is at present being undertaken has resulted in quantities of spoil being heaped around. This breaks up the entire outline of the area (see sketch at appendix). the corresponding position at the eastern end of the 25X1 taxiway gives the impression that a similar hardstanding of approximately equal proportions is about to be constructed there. 25X1

Sanitized Copy Approved for Release 2010/06/16: CIA-RDP80T00246A037200270001-9

	SECRET	25 X 1
	-2-	25X1
		20/(1
)	The site of the hardstanding located north of the parallel taxiway is being prepared,	
	ready for concreting. This excavation is approximately 40 cms	25
	in depth and has an overall length of approximately 950 m	25
	The western end terminates at the readway At this	
	point a new taxiway/roadway is being laid	
	down in a westerly direction - final length is unknown. The exact site and dimensions of the connecting lanes extending	
	between this hardstanding and the parallel taxiway is at present	
	hard to define. It will be possible to ascertain this when the	
	concreting commences and the number of intervening sections can	
	An underground storm water soak-away is being constructed around	
	the entire hardstanding, and	25
	a series of pipes is being laid underground, identical to the	20
	system bordering the entire main runway. The southern pipeline	
	bordering this hardstanding lies further back than the others and is north of the edge of the	
	(possible hardstanding) area adjoining the eastern end of the	OEV.4
	parallel taxiway.	25 X 1
	The storm water from this hardstanding is to be fed away into the	
	common soak-away adjoining the SE corner of the runway (for approximate position see sketch attached).	
	Construction of this main hardstanding and associated taxidays is	
	about to commence and the guide rails for the concrete-laying	
	machines have been laid.	
	POWER CABLES	
)	Two pipelines, each having a diameter of approximately 10 cms.,	
•	have been laid through the two westerly transverse taxivays -	
	up from the runway. It is not known	25
	whether there are similar pipes in a corresponding position in the easterly transverse taxitracks.	
	A power cable of 15,000 volts extending along the eastern perimeter	
	of the airfield has recently been disturbed during excavation for	
	the pipelines in the storm water outlet system.	
)	There is a permanent, brick-built transformer located at	
•	approximately the main material storage and	25
	mixing site. This transformer is linked to two single, underground	
0 0 a 1 t	power cables of unknown capacity, which extend across the airfield. One crosses approximately midway along the runway/taxiway, terminating	
	on the southern side of the runway. There is no building at present	
	anywhere near the terminal of this cable. The other power cable	
	leads off in a SEly direction, again crossing under the runway and taxiway, passing out of the airfield perimeter in the direction	
	of STENDAL.	
	MEW FUEL INSTALLATION	
	The new fuel installation is to be constructed on the site of the	
	ting material storage/mixing site located where the	25
	nt storage shed and adjoining material storage sheds all have very	
	d concrete bases. As soon as the construction of the new hard- ding and its associated taximays has been completed (estimated for	
	end of September) the cement storige shed is to be dismantled.	
	The firm K.B.U. STENDAL is scheduled to commence the construction	
	his new fuel depot as soon as the site has been cleared.	
	permanent airfield rail spur which formerly terminated at this	
X1	ng point has been extended further SEwards and terminated at where there is a series of sidings and	0.5
jo	ining ramps. More details of this final portion of the rail spur	25
	be obtained as soon as possible.	
	SECRET CONTROL	
	o organic aniv	25X

4.

5.

Sanitized Copy Approved for Release 2010/06/16 : CIA-RDP80T00246A037200270001-9

् हें बु

- 3 -

25X1

SURFACE CONSTRUCTION

6.

- (a) An extensive surface construction programme is scheduled to commence on and around the existing technical site bordering the northern perimeter of the airfield landing area. The two main hangars at present used by the BAU UNION BRANDENBURG are shortly to be cleared completely of all materials and equipment. Complete renovation of these two hangars is scheduled to take place the two ov rhead cranes extending along both roofs have already been completely overhauled. The nature of the building programme and the contracting firms concerned is not as yet known, but it is definitely not being undertaken by the BAU UNION BRANDENBURG. There are rumours that the BAU UNION BERLIN will be one of the contractors concerned.
- (b) No further development of the excavation adjoining the main entrance in the NE corner of the airfield has taken place. There are still no signs of any building materials in the vicinity which would indicate the nature of any proposed construction at this point.
- (c) An inspection of the wooded area adjoining the NW perimeter of the cirfield on the readway to the village of PEULINGEN has shown it to be inactive and there are no signs of any new construction in the immediate vicinity.

SECRET GONTROL U. S. OFFICIALS GNLY

SECRET

